



# Component-Equipment-List

TNK  
15:09

14.Jan.2015  
Page 1/7

P/N: 201375009-110 S/N:M-DG-0989 (A320 - MLG - LH)

TSN 53858 H  
CSN 18873 C

Installed on AHHH. Only rotatables with requirements with subtrees, group by 2 char. on ATA-Chapter ( A/C Data: 54'854/H, 19'010/C )

| ATA | Description  | Partno      | Serialno  | Description                 | Pos.       | Release no. / Label no. | Inst-Date       | TSN        | CSN          |
|-----|--------------|-------------|-----------|-----------------------------|------------|-------------------------|-----------------|------------|--------------|
| 32  | LANDING GEAR | 00-200-1482 | SMOLS5    | UPPER CARDAN NUT            | MLG/L<br>H | - / 909540              | 13.Nov.2007     | 18502      | 6654         |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |              |             |           |                             |            | SCRAP                   | 60000/C         | 6654/C     | 53346 / C    |
|     |              | 114193008   | B922      | RETRACTION ACTUATOR         | MLG/L<br>H | - / 909558              | 28.Aug.2013     | 45794      | 35130        |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |              |             |           |                             |            | SCRAP                   | 60000/C         | 35130/C    | 24870 / C    |
|     |              | 114193602   | S1141B922 | MLG GLAND                   | MLG/L<br>H | - / 909562              | 28.Aug.2013     | 45794      | 35130        |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |              |             |           |                             |            | SCRAP                   | 60000/C         | 35130/C    | 24870 / C    |
|     |              | 201056909   | MG07146   | MLG LOCK STAY CARDAN<br>PIN | MLG/L<br>H | - / 909556              | 13.Nov.2007     | 53858      | 18873        |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |              |             |           |                             |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |              | 201057306   | S6611B662 | TRIANGULATION LINK          | MLG/L<br>H | - / 909542              | 13.Nov.2007     | 53858      | 18873        |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |              |             |           |                             |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |              | 201057611   | S6611B662 | MLG SPRING - UPPER PIN      | MLG/L<br>H | - / 909651              | 13.Nov.2007     | 53858      | 18873        |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |              |             |           |                             |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |              | 201057624   | S6611B662 | TRIANGULATION LINK PIN      | MLG/L<br>H | - / 909541              | 13.Nov.2007     | 53858      | 18873        |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |              |             |           |                             |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |              | 201057625   | S6611B662 | LOWER PIN - SPRINGS         | MLG/L<br>H | - / 909652              | 13.Nov.2007     | 53858      | 18873        |
|     |              |             |           |                             |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |



# Component-Equipment-List

TNK  
15:09

14.Jan.2015  
Page 2/7

P/N: 201375009-110 S/N:M-DG-0989 (A320 - MLG - LH)

Installed on AHHH. Only rotatables with requirements with subtrees, group by 2 char. on ATA-Chapter ( A/C Data: 54'854/H, 19'010/C )

| ATA | Description | Partno    | Serialno  | Description                    | Pos.       | Release no. / Label no. | Inst-Date       | TSN        | CSN          |
|-----|-------------|-----------|-----------|--------------------------------|------------|-------------------------|-----------------|------------|--------------|
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201057627 | MN1120    | MLG LOCK LINK LOWER PIN        | MLG/L<br>H | - / 909549              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |           |                                |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201057644 | S6611B662 | PIN - LOCK LINK/BANANA<br>LINK | MLG/L<br>H | - / 909548              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |           |                                |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201058003 | B1393     | LOCK LINK                      | MLG/L<br>H | - / 909550              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |           |                                |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201058304 | MN1030    | LOCK STAY CARDAN               | MLG/L<br>H | - / 909555              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |           |                                |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201058305 | MN1086    | MLG LOWER LOCK LINK            | MLG/L<br>H | - / 909551              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |           |                                |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201058310 | MN1049    | MLG UPPER LOCK LINK            | MLG/L<br>H | - / 909553              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |           |                                |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201058608 | MN1044    | MLG LOCK LINK CENTER PIN       | MLG/L<br>H | - / 909552              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |           |                                |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |           |                                |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201058611 | MN1141    | MLG LOCK LINK UPPER PIN        | MLG/L<br>H | - / 909554              | 13.Nov.2007     | 53858      | 18873        |



# Component-Equipment-List

TNK  
15:09

14.Jan.2015  
Page 3/7

P/N: 201375009-110 S/N:M-DG-0989 (A320 - MLG - LH)

Installed on AHHH. Only rotatables with requirements with subtrees, group by 2 char. on ATA-Chapter ( A/C Data: 54'854/H, 19'010/C )

| ATA | Description | Partno    | Serialno   | Description                    | Pos.       | Release no. / Label no. | Inst-Date   | TSN     | CSN       |
|-----|-------------|-----------|------------|--------------------------------|------------|-------------------------|-------------|---------|-----------|
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18873/C | 41127 / C |
|     |             | 201160304 | M488/16    | CARDAN BRACKET - LH            | MLG/L<br>H | - / 909517              | 13.Nov.2007 | 39628   | 18087     |
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18087/C | 41913 / C |
|     |             | 201160325 | SER5705/97 | LOWER TORQUE LINK - A320       | MLG/L<br>H | - / 909527              | 13.Nov.2007 | 53858   | 18873     |
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18873/C | 41127 / C |
|     |             | 201160328 | SER5747/97 | UPPER TORQUE LINK - A320       | MLG/L<br>H | - / 909524              | 13.Nov.2007 | 53858   | 18873     |
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18873/C | 41127 / C |
|     |             | 201160329 | SER3965/97 | MAIN FITTING - A320 LH         | MLG/L<br>H | - / 909522              | 13.Nov.2007 | 53858   | 18873     |
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18873/C | 41127 / C |
|     |             | 201160602 | SER7386/97 | MLG LOWER TORQUE LINK<br>PIN   | MLG/L<br>H | - / 909528              | 13.Nov.2007 | 53858   | 18873     |
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18873/C | 41127 / C |
|     |             | 201160603 | SER7377/97 | UPPER TORQUE LINK PIN          | MLG/L<br>H | - / 909523              | 13.Nov.2007 | 53858   | 18873     |
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18873/C | 41127 / C |
|     |             | 201160697 | SER5658/97 | TORQUE LINK APEX PIN -<br>A320 | MLG/L<br>H | - / 909525              | 13.Nov.2007 | 53858   | 18873     |
|     |             |           |            |                                |            | Requirement             | Interval    | TSR     | To go     |
|     |             |           |            |                                |            | SCRAP                   | 60000/C     | 18873/C | 41127 / C |



# Component-Equipment-List

TNK  
15:09

14.Jan.2015  
Page 4/7

P/N: 201375009-110 S/N:M-DG-0989 (A320 - MLG - LH)

Installed on AHHH. Only rotatables with requirements with subtrees, group by 2 char. on ATA-Chapter ( A/C Data: 54'854/H, 19'010/C )

| ATA | Description | Partno    | Serialno     | Description                        | Pos.       | Release no. / Label no. | Inst-Date       | TSN        | CSN          |
|-----|-------------|-----------|--------------|------------------------------------|------------|-------------------------|-----------------|------------|--------------|
|     |             | 201160700 | S7509MDG0989 | TORQUE LINK APEX PIN NUT<br>- A320 | MLG/L<br>H | - / 909526              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |              |                                    |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201163300 | MN1032       | MLG UPPER SIDE STAY                | MLG/L<br>H | - / 909537              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |              |                                    |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201163301 | MN965        | MLG LOWER SIDE STAY                | MLG/L<br>H | - / 909535              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |              |                                    |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201163307 | B43-1659     | LOWER CARDAN                       | MLG/L<br>H | - / 909516              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |              |                                    |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201163609 | MN1071       | MLG SIDE STAY PIVOT PIN            | MLG/L<br>H | - / 909536              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |              |                                    |            | SCRAP                   | 60000/C         | 18873/C    | 41127 / C    |
|     |             | 201163618 | SR1121       | MLG SIDE STAY UPPER<br>CARDAN PIN  | MLG/L<br>H | - / 909538              | 13.Nov.2007     | 18502      | 6654         |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |              |                                    |            | SCRAP                   | 60000/C         | 6654/C     | 53346 / C    |
|     |             | 201163619 | MNAS378      | MLG SIDE STAY LWR CARDAN<br>PIN    | MLG/L<br>H | - / 909534              | 13.Nov.2007     | 18502      | 6654         |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |              |                                    |            | SCRAP                   | 60000/C         | 6654/C     | 53346 / C    |
|     |             | 201163620 | B29-6        | MLG UPPER CARDAN                   | MLG/L<br>H | - / 909539              | 13.Nov.2007     | 53858      | 18873        |
|     |             |           |              |                                    |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |



# Component-Equipment-List

TNK  
15:09

14.Jan.2015  
Page 5/7

P/N: 201375009-110 S/N:M-DG-0989 (A320 - MLG - LH)

Installed on AHHH. Only rotatables with requirements with subtrees, group by 2 char. on ATA-Chapter ( A/C Data: 54'854/H, 19'010/C )

| ATA | Description | Partno        | Serialno   | Description             | Pos.       | Release no. / Label no. | Inst-Date       | TSN         | CSN          |
|-----|-------------|---------------|------------|-------------------------|------------|-------------------------|-----------------|-------------|--------------|
|     |             |               |            |                         |            | SCRAP                   | 60000/C         | 18873/C     | 41127 / C    |
|     |             | 201163945     | 2259/07    | MLG LOWER CARDAN NUT    | MLG/L<br>H | - / 909533              | 13.Nov.2007     | 18502       | 6654         |
|     |             |               |            |                         |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b>  | <b>To go</b> |
|     |             |               |            |                         |            | SCRAP                   | 60000/C         | 6654/C      | 53346 / C    |
|     |             | 201166013     | B662       | SIDESTAY ASSY, MLG      | MLG/L<br>H | - / 909532              | 13.Nov.2007     | 53858       | 18873        |
|     |             |               |            |                         |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b>  | <b>To go</b> |
|     |             |               |            |                         |            | OVERHAUL                | 3650/D          | 13.Nov.2007 | 1031 / D     |
|     |             |               |            |                         |            | OVERHAUL                | 20000/C         | 18873/C     | 1127 / C     |
|     |             | 201173600     | SER6891/97 | MLG FWD PINTLE PIN      | MLG/L<br>H | - / 909519              | 13.Nov.2007     | 53858       | 18873        |
|     |             |               |            |                         |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b>  | <b>To go</b> |
|     |             |               |            |                         |            | SCRAP                   | 60000/C         | 18873/C     | 41127 / C    |
|     |             | 201371247     | B180-4626  | SHOCK ABSORBER          | MLG/L<br>H | - / 909529              | 13.Nov.2007     | 53858       | 18873        |
|     |             |               |            |                         |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b>  | <b>To go</b> |
|     |             |               |            |                         |            | RESTORATION             | 3650/D          | 13.Nov.2007 | 1031 / D     |
|     |             |               |            |                         |            | RESTORATION             | 20000/C         | 6654/C      | 13346 / C    |
|     |             | 201371302     | B184-1873  | SLIDING TUBE - A320 MLG | MLG/L<br>H | - / 909530              | 13.Nov.2007     | 45359       | 17721        |
|     |             |               |            |                         |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b>  | <b>To go</b> |
|     |             |               |            |                         |            | SCRAP                   | 60000/C         | 17721/C     | 42279 / C    |
|     |             | 201371615     | 07B0272X7  | UPPER DIAPHRAGM TUBE    | MLG/L<br>H | - / 909531              | 13.Nov.2007     | 18502       | 6654         |
|     |             |               |            |                         |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b>  | <b>To go</b> |
|     |             |               |            |                         |            | SCRAP                   | 60000/C         | 6654/C      | 53346 / C    |
|     |             | 201375009-110 | M-DG-0989  | A320 - MLG - LH         | MLG/L<br>H | - / 909515              | 13.Dec.2007     | 53858       | 18873        |
|     |             |               |            |                         |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b>  | <b>To go</b> |
|     |             |               |            |                         |            | RESTORATION             | 3650/D          | 13.Dec.2007 | 1061 / D     |

*L. Kal*  
*Toski*



# Component-Equipment-List

TNK

15:09

14.Jan.2015

Page 6/7

P/N: 201375009-110 S/N:M-DG-0989 (A320 - MLG - LH)

Installed on AHHH. Only rotatables with requirements with subtrees, group by 2 char. on ATA-Chapter ( A/C Data: 54'854/H, 19'010/C )

| ATA | Description | Partno    | Serialno        | Description                   | Pos.       | Release no. / Label no. | Inst-Date       | TSN        | CSN          |
|-----|-------------|-----------|-----------------|-------------------------------|------------|-------------------------|-----------------|------------|--------------|
|     |             |           |                 |                               |            | RESTORATION             | 20000/C         | 6654/C     | 13346 / C    |
|     |             | 201540609 | S7509MDG0989    | FORWARD PINTLE PIN STUB BOLTS | MLG/L<br>H | - / 909520              | 13.Nov.2007     | 39812      | 14082        |
|     |             |           |                 |                               |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |                 |                               |            | SCRAP                   | 60000/C         | 14082/C    | 45918 / C    |
|     |             | 201540609 | S7509MDG09892   | FORWARD PINTLE PIN STUB BOLTS | MLG/L<br>H | - / 909521              | 13.Nov.2007     | 39812      | 14082        |
|     |             |           |                 |                               |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |                 |                               |            | SCRAP                   | 60000/C         | 14082/C    | 45918 / C    |
|     |             | 201661302 | S6611B662       | CUFF                          | MLG/L<br>H | - / 909547              | 13.Nov.2007     | 34912      | 12413        |
|     |             |           |                 |                               |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |                 |                               |            | SCRAP                   | 60000/C         | 12413/C    | 47587 / C    |
|     |             | 201661304 | S6611B662       | BANANA LINK - SPRINGS         | MLG/L<br>H | - / 909543              | 13.Nov.2007     | 34912      | 12413        |
|     |             |           |                 |                               |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |                 |                               |            | SCRAP                   | 60000/C         | 12413/C    | 47587 / C    |
|     |             | 201661304 | S6611B6622      | BANANA LINK - SPRINGS         | MLG/L<br>H | - / 909544              | 13.Nov.2007     | 34912      | 12413        |
|     |             |           |                 |                               |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |                 |                               |            | SCRAP                   | 60000/C         | 12413/C    | 47587 / C    |
|     |             | 201661612 | 06MAM20140X19   | MLG CUFF PIN                  | MLG/L<br>H | - / 909545              | 13.Nov.2007     | 18502      | 6654         |
|     |             |           |                 |                               |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |                 |                               |            | SCRAP                   | 60000/C         | 6654/C     | 53346 / C    |
|     |             | 201661612 | 06MAM20140X27   | MLG CUFF PIN                  | MLG/L<br>H | - / 909546              | 13.Nov.2007     | 18502      | 6654         |
|     |             |           |                 |                               |            | <b>Requirement</b>      | <b>Interval</b> | <b>TSR</b> | <b>To go</b> |
|     |             |           |                 |                               |            | SCRAP                   | 60000/C         | 6654/C     | 53346 / C    |
|     |             | 450239404 | 07NM043860X1008 | AFT PINTLE SPHERICAL BEARING  | MLG/L<br>H | - / 909518              | 13.Nov.2007     | 18502      | 6654         |

