



14544743

1. Approving Competent Authority / Country LBA / Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 11031378 00000002	
4. Approved Organisation Name and Address: Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 P.O. Box 63 03 00 D-22313 Hamburg Federal Republic of Germany				5. Work Order/Contract/Invoice 14544743	
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work
01	ACTUATOR RETRACTION MLG	114193008	1	B922	OVERHAULED
12. Remarks FSCM K0654. ATA 3231 TP O MK-No. 10 Pack Code XZ Resp. Workshop 32243010 Workshop Station HAM017 SBC : 200-32-284 : R/I 00 : 20040801 performed. SBC : 200-32-295 : R/I 00 : 20060703 performed. Following LLP's installed: Main Pin 114193637 / DLH62912 (TC:34183) Rear Pin 114193610 / DLH62911 (TC:34183) Gland 114193602 / S1141B922 (TC:34183) Head 114193603 / S1141B922 (TC:34183) Nut 114193604 / S1141B922 (TC:34183) Cylinder 114193600 / S1141B895 (TC:23646) Rod 114193601 / S2015B555 (TC:12215) TASK PERFORMED IN ACCORDANCE WITH CMM 32-31-47 REV 31 / CMMDS 32-31-47 ISSUE 31 For storage conditions see CMM or operator's maintenance program. Limited life parts must be accompanied by maintenance history including total time/total cycle/time since new. 13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☒ Part 145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service. 13b. Authorised Sign 13c. Certification Number 13d. Name 14a. Certificate / Approval Ref. Number 14b. Authorised Signature 14c. Date (dd mm yyyy) 14d. Name 14e. Date (dd mm yyyy)					

EASA FORM 1 - Issue 2
USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Log ref:	BFY 181/24-1
Date:	29.08.2013
Reg:	VP-BFY
Station:	VVO
SIN off:	B434
PIN off:	14493008
Pos:	2504 GM
Tag No:	1103131800000002
TEN:	52576'58
TFC:	1063

VLADIVOSTOK AIR

WORK ORDER

ED 00002441 Miscellaneous

Opened on	Cny	Center	Place	Type	Reference
18/07/2013	VLK	ED	VLK ED	6	MLG RETRACTION ACTUATORS RE
ATA	Control	Repetitive W.O.	H.I.L	ETOPS	
32-31	Inspection requested	NO		NO	
A/C Reg	Part Number	Serial Number	Description		
VP-BFY					
Skill.	Station	Phase	Zone	Maintenance level	
32576.58	FH/8063CY	Check	Date	Estimated Time	
Scheduled			26/07/2013	24,00	
REQUESTED WORK		PERFORMED WORK		Mec.	Ctl.
Replace the both MLG Retraction Actuators 114193008 s/n B437 and B1018 Write down installed LH and RH actuators p/n and s/n		Replaced Retraction actuators LH S/n B1018 Installed LH actuator P/n 114193008 S/n B331		VA33	
Bleeding off actuating cylinders not performed Retraction/Extension Test not performed		Retraction Actuators R/H Replace ment performed aceto AMM 32-31-46 PB401. Seal Mas be en applied Greasing must be performed after Sealant all dry		VA03	
Bleeding off JAW 32-31-46-600-001 GREASING JAW 12-22-32-640-001 RETRACTION/EXTENSION Test JAW 32-31-00-720-002-A					
ATL BFY 181/24-01					
VLADIVOSTOK AIR J.S.C., hereby certifies that in carrying out the maintenance specified above, all requirements in the Air Navigation Regulations which are applicable thereto have been complied with Reference Air Navigation Regulations, 1976, Chapter 15, 6					
at	WVO	on the	30.08.73	Hour	18:00
Signature		Name		Khlobutin	
* : nycer la inscruon iustice		VN-39			
					
IFR Printed thanks to the IFR France AMASIS system					
Printed on août 28, 2013					
Page 1/2					

29 AUG 2013

WORK ORDER

ED 00002441 Miscellaneous

Opened on Cny Center Place Type Reference
18/07/2013 VLK ED VLK ED 6 MLG RETRACTION ACTUATORS RE

Position	P/N OFF	S/N OFF	P/N ON	S/N ON
25056M	114193 008	B10 18	114193 008	B331
25046M	114193008	B434	114193008	B922

MATERIAL(S) & TOOL(S) REQUIRED

Part Number	Description	Required Qty	A.U.
IN Ingredient			
PR1422B2	SEALANT	1	A.U.
Part Number			
SP Spare part			
MS24665-155	PIN STEEL	2	
MS24665-302	cotter pins	1	

REFERENCE(S)

Doc. Type	Protocol Reference	Rev.	Item Nbr	Page Nbr	Description
EO	A320 164		00		

LABOUR

Date
Salary No
Time



29 AUG 2013

 VLADIVOSTOK AIR			ENGINEERING ORDER					
Customer	AWN	Product	Contractor	EO-Class	EO-Type	EO-Number	Issue	ATA
VLK		W		A		164	00	32

*	**	Pages	Issue Date	*	**	Pages	Issue Date
E		1-1, 1-2	18 Jul 13				
L		1-LEP	18 Jul 13				
E		4-10- AMM TASK	01 Feb 13				
		32-31-46-000-001-A					
		11-19- AMM TASK	01 Feb 13				
E		32-31-46-400-001-A					
		20 - AMM TASK	01 Feb 13				
		32-00-00-860-001-A					
E		21-26- AMM TASK	01 Feb 13				
		32-31-00-720-001-A					
E		27 29- AMM TASK	01 Feb 13				
		32-00-00-860-002-A					

*A = Added D = Deleted R = Revised
 **A = AEB C = Check List E = Engineering Order L = LEP S = SB/SL W = Economical Evaluation X = Engineering/TK only

Date of Issue	18 Jul 2013	Page 3-29
---------------	-------------	-----------

 VLADIVOSTOK AIR			ENGINEERING ORDER					
Customer	AWN	Product	Contractor	EO-Class	EO-Type	EO-Number	Issue	ATA
VLK		W		A		164	00	32
Subject: Replacement of MLG Retraction Actuator								
Authority Requirement N/A								
References AMM								
Reason for revision N/A								
Note Description Replacement of MLG Retraction Actuator.								
Modification/ Repair			No					
Airworthiness Approval			No					
Effectivity			A320					
Warranty			NO			Materials No Man-hours		
Remarks								
Dept			Name		Phone		Fax	
Prod. Planning			Darya Khlebutina		+74232307708			
Add. Prod. Planning								
Mat. Planning			Ivan Vlaskin		+74232307039			
Add. Mat. Planning								
Add. PEP's								
Dept			Name		Phone		Fax Date Signature	
Prepared by Engineering			Konstantin Gulyaev		+74232307716			
Released by								
Approved by Engineering			Alexander Goverdovsky		+74232307713			
Approval Document								
Date of Issue			18 Jul 2013					
								Page 1-29

 VLADIVOSTOK AIR			ENGINEERING ORDER																																			
Customer	AWN	Product	Contractor	EO-Class	EO-Type	EO-Number	Issue	ATA																														
VLK		W		A		164	00	32																														
Planning Data																																						
<table border="0"> <tr> <td>Material</td> <td></td> <td></td> <td></td> <td>Remarks</td> </tr> <tr> <td>PR1422B2</td> <td>sealant</td> <td></td> <td></td> <td></td> </tr> <tr> <td>MS24665-155</td> <td>cotter pin</td> <td>2 ea</td> <td></td> <td></td> </tr> <tr> <td>MS24665-302</td> <td>cotter pin</td> <td>1 ea</td> <td></td> <td></td> </tr> </table>									Material				Remarks	PR1422B2	sealant				MS24665-155	cotter pin	2 ea			MS24665-302	cotter pin	1 ea												
Material				Remarks																																		
PR1422B2	sealant																																					
MS24665-155	cotter pin	2 ea																																				
MS24665-302	cotter pin	1 ea																																				
Check Items	Item	Remarks																																				
N/A																																						
		Weight	Unit	Moment	Unit	STA																																
<table border="0"> <tr> <td>Affected Documents</td> <td>Doc affected</td> <td>Remarks</td> <td>Doc affected</td> <td>Remarks</td> </tr> <tr> <td>AMM TASK 32-31-46-000-001-A</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AMM TASK 32-31-46-400-001-A</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AMM TASK 32-00-00-860-001-A1</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AMM TASK 32-31-00-720-001-A</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AMM TASK 32-00-00-860-002-A</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>									Affected Documents	Doc affected	Remarks	Doc affected	Remarks	AMM TASK 32-31-46-000-001-A					AMM TASK 32-31-46-400-001-A					AMM TASK 32-00-00-860-001-A1					AMM TASK 32-31-00-720-001-A					AMM TASK 32-00-00-860-002-A				
Affected Documents	Doc affected	Remarks	Doc affected	Remarks																																		
AMM TASK 32-31-46-000-001-A																																						
AMM TASK 32-31-46-400-001-A																																						
AMM TASK 32-00-00-860-001-A1																																						
AMM TASK 32-31-00-720-001-A																																						
AMM TASK 32-00-00-860-002-A																																						
Additional Copies to																																						
Date of Issue			18 Jul 2013				Page 2-29																															